



4.8V Cordless Screwdriver Set

PCS4.8V

QUICK START GUIDE

Easy steps to getting started

1. Remove your PCS 4.8v from the packaging ensuring that you have all the accessories and parts.
2. Connect your PCS 4.8v to the charger unit supplied and plug this in to an electric outlet and allow to charge for 5 Hours. Once fully charged disconnect the charger to the PCS4.8v.

REMEMBER DO NOT LEAVE THIS UNIT ON CHARGE FOR LONGER THAN STATED. THIS CHARGER DOES NOT SWITCH OFF AUTOMATICALLY ONCE BATTERY IS FULLY CHARGED. OVER CHARGING CAN RESULT IN DAMAGING THE BATTERY.

3. With the lock switched on. Firmly insert the magnetic bit holder provided to the head of the PCS4.8v. Select the required drill bit for your task and insert securely into the bit holder ensuring that the drill bit head is facing outwards.

NOTE THAT ONLY THE DRILL BITS PROVIDED ARE TO BE USED WITH THE PCS4.8V.

4. Adjust the handle to a comfortable working position.

Your PCS 4.8v is now ready for use.

IF IN DOUBT PLEASE REFER TO THE MANUAL PROVIDED.