



2100W Metal Cut Off Saw BT-MC 355

QUICK START GUIDE

Easy steps to getting started.

1. Ensure all items, including your user guide are removed from the packaging before discarding.
2. To unlock the saw head (1) from its lower position, push the saw head (1) down with the handle (2) and pull out the locking device (13). Note: Slowly rise the saw head (1) by applying slight pressure to the handle (2).
3. Fasten your workpiece in the vice (15). Refer to Section 8.2 of the User Guide for more detail.
4. To perform mitre cuts, swivel the vice (15) to the required angle. Refer to Section 8.3 of the User Guide for more detail.
5. To start the saw, press the safety lock (b), then press the ON/ OFF switch (10). Keep the ON/OFF switch (10) pressed while you are sawing. To stop the saw, let go of the ON/ OFF switch (10).
6. To make a cut, let the saw reach its full speed, push down the saw head (1) by the handle (2) until the cut-off wheel (11) makes slight contact with the workpiece. Press down the handle (2) firmly and evenly and move the cut-off wheel (11) smoothly through the material you want to cut. Note: Do not reduce cutting speed at the end of cutting operation.
7. The cut-off wheel gets smaller in diameter as it is used. To compensate the wheel wear the cut-off wheel can be adjusted in height as described in Section 8.4 of the User Guide.
8. **IF YOU ARE IN ANY DOUBT PLEASE REFER TO THE DETAILED INSTRUCTIONS WITHIN THE USER GUIDE.**

